


BEST AVAILABLE COPY









Fig. 3







PCT/US2003/036770

WO 2004/046707




Fig. 5

The state of the s





Fig. 6






Fig. 8




Fig. 9





Fig. 10






Fig. 11

Sensor Array N1B-4-3; Sensor #5




Fig. 12

Sensor Array N1F-8-3; Sensor #14




Fig. 13




Fig. 14

15/62




Fig. 15




Fig. 16

PCT/US2003/036770

Cyclic Voltammogram




Fig. 17




Fig. 18

Sensor Array N1F-8-3; Sensor #0




Fig. 19

20/62




Fig. 20





Fig. 21






Fig. 22

CHUZ ARROY OTHER PROPERTY

23/62




Fig. 23

Superimposed Cyclic Voltammograms




Fig. 24




Fig. 25





Fig. 26






Fig. 27




Fig. 28

29/62




Fig. 29




Fig. 30






Fig. 31




Fig. 32




Fig. 33

34/62






Fig. 34




Fig. 35




Fig. 36




Fig. 37




Fig. 38




Fig. 39




Fig. 40




Fig. 41




Fig. 42




Fig. 43




Fig. 44




Fig. 45




Fig. 46





Fig. 47






Fig. 48

WO 2004/046707

49/62

PCT/US2003/036770




Fig. 49




Fig. 50

PCT/US2003/036770




Fig. 51




Fig. 52






Fig. 53





ARCH PURCE CO.




Fig. 54




Fig. 55

PCT/US2003/036770




Fig. 56




Fig. 57 A-F




Fig. 58





Fig: 59






Fig. 60

WO 2004/046707






Fig. 61

TANKE TOO




Fig. 62

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

BLACK BORDERS	· ·
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES	
☐ FADED TEXT OR DRAWING	
BLURRED OR ILLEGIBLE TEXT OR DRAWING	
SKEWED/SLANTED IMAGES	
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS	5
☐ GRAY SCALE DOCUMENTS	
☐ LINES OR MARKS ON ORIGINAL DOCUMENT	, e,
REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE	E POOR QUALITY
OTHER:	

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.